46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

EA18HNW

Renault Captur 0.9 TCE 90 Dynamique Nav 5dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	28/03/2018	**Body Style**	Hatchback	**Last service miles**	4
Year	2018	**Keys**	1	**MOT Due**	30/03/2026
Mileage	78,197 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	Petrol	**Service documents**	Printout	**Gears**	5
Colour	BLACK/CREAM	**Number of stamps**	4	**Doors**	5
VIN	VF12RA51559861956	**Last service date**	28/01/2026		

£100 ADDITIONAL FEE
last service 28/1/26 mileage not recorded (4 services) print Engine tapping noise

Tyres

NSF	BUDGET	5.0mm
NSR	ROADSTONE	4.0mm
OSF	FARROAD	5.0mm
OSR	ROADSTONE	4.0mm
Spare		

Features

- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Digital radio
- Space saver spare wheel
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- PAS
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels

Photos

EA18 HNW

1 58
Destination
Seahaven
AUTO
A/C

COLOUR BLACK
EA18 HNW

FM
05
1 58
Seahaven
Varied
95.6 MHz
Sunny - Boney M
Main
List
Presets
Options
AUTO
A/C





Condition Check



Damage Photos

1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Poor Previous Repair
Paint Flake

3: Wing Front Arch Extension os
Scuffed (Unpainted)
UpTo 100mm

4: Wing osf
Scratched
Over 25mm Thru Paint

5: Wheel osf
Scratched
Over 50mm

6: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint

7: Door osf
Dented
With Paint Damage

8: Door osr
Dented
With Paint Damage

9: Wheel osr
Scratched
Over 50mm

10: Qtr Panel osr
Dented
Between 10mm + 30mm

11: Qtr Panel osr
Scratched
Over 25mm Thru Paint

12: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm

13: Bumper Rear
Scratched
25 to 100mm Thru Paint

14: Tailgate
Scratched
Over 25mm Thru Paint

15: Qtr Panel nsr
Dented
Between 10mm + 30mm

16: Qtr Panel osr
Scratched
Over 25mm Thru Paint

17: Wheel nsr
Scratched
Over 50mm



18: Door nsr
Chipped
1 To 5

19: Door nsf
Dented
With Paint Damage

20: Wing osf
Scratched
UpTo 25mm Thru Paint

21: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK