46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

DT18OZN

Vauxhall Astra 1.6 CDTi 16V ecoTEC Tech Line Nav 5dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	31/08/2018	**Body Style**	Estate	**Last service miles**	58,449
Year	2018	**Keys**	2	**MOT Due**	09/09/2026
Mileage	58,746 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	Diesel	**Service documents**	Printout	**Gears**	6
Colour	BLUE	**Number of stamps**	1		
VIN	W0VBD8EL2J8074205	**Last service date**	29/10/2025		

Last service 29/10/2025 at 58,449 miles- 1 service. Print

Tyres

NSF	MAZZINI	6.0mm
NSR	CONTINENTAL	5.0mm
OSF	MAZZINI	6.0mm
OSR	BUDGET	5.0mm
Spare		

Features

- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Navigation system
- Digital radio
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- PAS
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels

Photos

Off Road
RADIO
BACK
MENU
HOME
MEDIA

AUDIO
PHONE
PROJECTION
NAV
SETTINGS
TEXT
TRAFFIC
RADIO
BACK
MENU
HOME
MEDIA


04



Condition Check



Damage Photos

1: Bonnet
Dented
Over 30mm

2: Bumper Front
Scratched
UpTo 25mm Thru Paint

3: Wheel nsf
Scratched
Over 50mm

4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint

6: Door nsf
Scratched
Over 25mm Thru Paint

7: Door nsf
Dented
Between 10mm + 30mm

8: Door nsr
Chipped
Multiple Chips

9: Wheel nsr
Scratched
Over 50mm

10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Roof
Dented
Over 30mm

12: Bumper Rear
Scratched
25 to 100mm Thru Paint

13: Tailgate
Scratched
UpTo 25mm Thru Paint

14: Qtr Panel osr
Dented
Between 10mm + 30mm

15: Qtr Panel osr
Scratched
Over 25mm Thru Paint

16: Wheel osr
Corroded
Light

17: Door osr
Poor Previous Repair
Rippled UpTo 30%

18: Door osf
Dented
With Paint Damage

19: Wheel osf
Scratched
Over 50mm

20: Wing osf
Chipped
1 To 5

21: B Post os
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK