46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

EO13YPA

Mercedes-Benz A Class A200 BlueEFFICIENCY Sport 5dr Auto

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	12/04/2013	**Body Style**	Hatchback	**Last service miles**	51,083
Year	2013	**Keys**	2	**MOT Due**	23/08/2026
Mileage	59,346 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
		Service documents	Printout	**Gears**	7
Fuel Type	Petrol	**Number of stamps**	6	**Doors**	5
Colour	BLACK	**Last service date**	25/08/2023		
VIN	WDD1760432J093677				

£100 ADDITIONAL FEE
Last service 25/08/2023 at 51,083 miles- 6 services (3 main dealer) Print
MOTs in 2021 and 2022 both recorded at 50,740 miles on MOT history EML light on car has been plugged in and indicates that the engine's coolant temperature is below the required operating temperature
Noisy engine pulley
Speedo clock is cracked

Tyres

NSF	BUDGET	5.0mm
NSR	MICHELIN	4.0mm
OSF	BUDGET	5.0mm
OSR	ROADSTONE	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Leather seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Metallic Paint
- Traction control
- Alloy wheels
- Front parking sensor
- Telephone
- Air conditioning
- Front electric windows
- ABS
- Central locking
- Heated front seat
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Remote central locking

Photos



8787.3
miles
59346
13.0°C

No navigation module is connected.

On Air Now on Heart: Matt Wilkinson

59282
E03 YPA


Reserve fuel level

Condition Check



Damage Photos

1: Other
N/A
N/A

2: Wheel osf
Corroded
Light

3: Door osf
Chipped
Multiple Chips

4: Door osr
Dented
With Paint Damage

5: Qtr Panel osr
Scratched
Over 25mm Thru Paint

6: Wheel osr
Corroded
Light

7: Bumper Rear
Scratched
Over 100mm Thru Paint

8: Qtr Panel nsr
Chipped
Over 5mm

9: Wheel nsr
Corroded
Light

10: Door nsr
Chipped
1 To 5

11: Door nsr
Chipped
Edge Chip

12: Door nsf
Dented
With Paint Damage

13: Wing nsf
Chipped
1 To 5

14: Wheel nsf
Corroded
Light

15: Bumper Front
Scratched
25 to 100mm Thru Paint

16: Bonnet
Chipped
Multiple Chips

17: A Post os
Chipped
1 To 5

18: A Post ns
Chipped
1 To 5

19: Bumper Front
Chipped
Multiple Chips

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK