46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

RO64CWL

Nissan Qashqai 1.2 DiG-T N-Tec+ 5dr Xtronic

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	20/10/2014	**Body Style**	Hatchback	**Last service miles**	81,294
Year	2014	**Keys**	2	**MOT Due**	20/10/2026
Mileage	84,065 Miles Warranted	**Service history**	Yes	**Gearbox**	CVT
		Service documents	Service Book	**Gears**	1
Fuel Type	Petrol	**Number of stamps**	11	**Doors**	5
Colour	SILVER	**Last service date**	24/09/2025		
VIN	SJNFEAJ11U1210786				

Last Service - 24.09.2025 at 81294 miles (11 main dealer services)

Tyres

NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Radio/CD
- Towbar
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos



Condition Check



Damage Photos

1: Bonnet
Chipped
1 To 5

2: Bumper Front
Scratched
25 to 100mm Thru Paint

3: Wing nsf
Dented
With Paint Damage

4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Chipped
Multiple Chips



6: Door nsf
Dented
Over 30mm

7: Wheel osf
Scratched
Over 50mm

8: Door nsr
Chipped
Multiple Chips

9: Bumper Rear
Scratched
25 to 100mm Thru Paint

10: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint

11: Wheel osr
Scratched
Over 50mm

12: Door osr
Dented
With Paint Damage

13: Door osf
Chipped
1 To 5

14: Wing osf
Chipped
1 To 5

15: Wheel osf
Scratched
Over 50mm



16: Screen Front
Cracked
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		