46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GY61VUE

Audi Q3 2.0 TDI [177] Quattro SE 5dr S Tronic

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	TBC

Details

Reg. date	29/11/2011	**Colour**	BLACK	**MOT Due**	29/11/2026
Year	2011	**VIN**	WAUZZZ8U9CR009057	**Gearbox**	SEMI AUTO
Mileage	38,706 Miles Warranted	**Body Style**	Estate	**Gears**	7
Fuel Type	Diesel	**Keys**	2		

£90 ADDITIONAL FEE

Tyres

NSF	PIRELLI	4.0mm
NSR	PIRELLI	4.0mm
OSF	BUDGET	3.0mm
OSR	PIRELLI	5.0mm
Spare		

Features

- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Leather seat trim
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking

Photos

Memory
Radio FM
Waveband
BBC R2
Pop
BBC R4
Social
BBCBuzzx
Varied
Classic
Light
Heart
Pop
Beethoven
Varied
Favourite
Return
Audi multimedia
TONE
RADIO
CAR
MEDIA
TEL
NAV
MENU
INFO

Audi multimedia
TONE
RADIO
CAR
MEDIA
TEL
NAV
MENU
INFO

Condition Check



Damage Photos

1: Door osf
Scratched
Over 25mm Thru Paint

2: Door osr
Scratched
Over 25mm Not Thru Paint

3: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

4: Bumper Rear
Scratched
Over 100mm Thru Paint

5: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

6: Door nsr
Scratched
Over 25mm Not Thru Paint

7: Door nsf
Scratched
Over 25mm Not Thru Paint

8: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint

9: Wing nsf
Scratched
Over 25mm Not Thru Paint

10: Bumper Front
Scratched
Over 25mm Not Thru Paint

11: Bonnet
Scratched
Over 25mm Not Thru Paint



12: Screen Front
Chipped
UpTo 10mm



13: Roof
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK