46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GX52NZM

Nissan Almera TWISTER

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	TBC

Details

Reg. date	05/09/2002	**Colour**	GREEN	**MOT Due**	04/06/2026
Year	2002	**VIN**	SJNFAAN16U0325023	**Gearbox**	MANUAL
Mileage	122,032 Miles Warranted	**Body Style**	Hatchback	**Gears**	5
		Keys	1	**Doors**	5
Fuel Type	Petrol				

Tyres

NSF	RAPID	5.0mm
NSR	RAPID	5.0mm
OSF	TOYO	5.0mm
OSR	RAPID	5.0mm
Spare		

Features

- Rear wiper
- Front electric windows
- Passenger airbag
- Steel wheels
- Radio/CD
- Rear headrests
- Central locking
- Body coloured bumpers
- Metallic Paint
- Remote central locking
- Air conditioning
- Drivers airbag
- Cloth seat trim

Photos



1024 FM

504

Condition Check



Damage Photos

1: Wing osf
Chipped
1 To 5

2: Wing osf
Scratched
UpTo 25mm Thru Paint

3: Door osf
Rusted
Over 5mm

4: Door osr
Scratched
Over 25mm Thru Paint

5: Qtr Panel osr
Dented
With Paint Damage

6: Bumper Rear
Poor Previous Repair
Paint Flake

7: Tailgate
Rusted
Over 5mm

8: Roof
Rusted
Over 5mm

9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

10: Door nsr
Rusted
Over 5mm

11: Door nsf
Rusted
Over 5mm

12: Wing nsf
Chipped
1 To 5

13: Wing nsf
Scratched
Over 25mm Not Thru Paint

14: Bumper Front
Cracked
Over 25mm

15: Bonnet
Chipped
Multiple Chips

16: Screen Front
Cracked
Replace

17: Sunvisor ns
Missing
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK
Airbag light illuminated	OK
ABS light illuminated	OK
Oil warning light illuminated	OK
Service indicator light illuminated	OK

Windows	OK
Radio	OK
Steering	OK