46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

HG65JSZ

Smart Forfour 0.9 Turbo Prime Premium 5dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	TBC

Details

Reg. date	20/01/2016	**Colour**	BROWN	**MOT Due**	10/08/2026
Year	2016	**VIN**	WME4530442Y025916	**Gearbox**	MANUAL
Mileage	65,152 Miles Warranted	**Body Style**	Hatchback	**Gears**	5
		Keys	2	**Doors**	5
Fuel Type	Petrol				

Bonnet and wing out of line

Tyres

NSF	BUDGET	5.0mm
NSR	LAUFENN	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features

- Bluetooth connection
- PAS
- Body coloured bumpers
- Front electric windows
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Front head restraints
- ABS
- Central locking
- Heated front seat
- Steering wheel mounted controls
- Electric sunroof
- Rear headrests
- Drivers airbag
- Remote central locking
- Navigation system
- Digital radio
- Air conditioning
- Metallic Paint
- Passenger airbag
- Leather seat trim

Photos

5:09 pm
0 km/h
10°C
5961.6
65152
miles

Heart - Pop music
Marshall Road
Brampton Road
Menu
Favourites

Condition Check



Damage Photos

1: Bumper Front
Insecure
Action Required

2: Headlamp os
Broken
Replace

3: Bumper Front
Scratched
25 to 100mm Thru Paint

4: Wheel nsf
Scratched
Over 50mm

5: Wing nsf
Chipped
1 To 5



6: Door nsf
Scratched
UpTo 25mm Thru Paint

7: Door osr
Scratched
UpTo 25mm Thru Paint

8: Wheel osr
Scratched
Over 50mm

9: Qtr Panel osr
Scratched
Over 25mm Thru Paint

10: Bumper Rear
Scratched
25 to 100mm Thru Paint

11: Wheel osr
Scratched
Up To 50mm

12: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint

13: Door osr
Dented
Between 10mm + 30mm

14: Door osf
Dented
Over 30mm

15: Door osf
Chipped
Edge Chip

16: Door osf
Scratched
UpTo 25mm Thru Paint

17: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK
Airbag light illuminated	OK
ABS light illuminated	OK
Oil warning light illuminated	OK
Service indicator light illuminated	OK

Roof / sunroof	OK
Windows	OK
Sat nav	OK
Radio	OK
Steering	OK