46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

BF15UOH

Ford Transit 2.2 TDCi 125ps H2 Van

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	19/06/2015	**Body Style**	Panel Van	**Last service miles**	137,422
Year	2015	**Keys**	2	**MOT Due**	31/10/2026
Mileage	169,710 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	Diesel	**Service documents**	Printout	**Gears**	6
Colour	WHITE	**Number of stamps**	9		
VIN	WF0XXXTTGXFK88683	**Last service date**	20/10/2025		

Last Service - 20.10.2025 at 176647 miles (9 services)
Gearbox, Clutch and DM Flywheel Replaced 23.05.2024 @ 137422 miles Service due now on dash EML light on has been plugged in and detects diesel particulate filter soot accumulation, a rocker arm actuator position sensor circuit low bank 1
Knocking from front when driving
Central locking not working on key

Tyres

NSF	FARROAD	6.0mm
NSR	SUNNY	6.0mm
OSF	SUNNY	6.0mm
OSR	SUNNY	6.0mm
Spare		

Features

- Bluetooth connection
- Towbar
- Central locking
- Front parking sensor
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Metallic Paint
- Media storage
- Drivers airbag

Photos

Ford
169710mls

12°C
Engine
Service now

FORD AUDIO

TRANSIT
15 PLATE



Condition Check



Damage Photos

1: Bonnet
Chipped
Multiple Chips

2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

3: Bumper Front
Insecure
Action Required

4: Bumper Front
Scratched
25 to 100mm Thru Paint

5: A Post ns
Dented
Over 30mm

6: Wing nsf
Chipped
1 To 5

7: Door nsf
Dented
With Paint Damage

8: Fuel Flap
Missing
Replace

9: Door nsr
Cracked
Replace

10: Sill Panel Trim ns
Missing
Replace



11: Qtr Panel nsr
Dented
Over 30mm

12: Tailgate
Dented
With Paint Damage

13: Qtr Panel osr
Dented
Between 10mm + 30mm

14: Qtr Panel Moulding os
Scuffed (Unpainted)
UpTo 100mm

15: Panel Front
Dented
Over 30mm

16: Door osf
Dented
Over 30mm

17: Wing osf
Scratched
Over 25mm Thru Paint

18: Wing Front Arch Extension os
Broken
Replace

19: Roof
Rusted
Over 5mm

20: Roof
Dented
With Paint Damage

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK