46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

AU23PFJ

Hyundai Tucson 1.6 TGDi Plug-in Hybrid Ultimate 5dr 4WD Auto

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	TBC

Details

Reg. date	13/07/2023	**Colour**	SILVER	**Gearbox**	AUTOMATIC
Year	2023	**VIN**	TMAJE812SPJ197987	**Gears**	6
Mileage	29,524 Miles Warranted	**Body Style**	Estate		
		MOT Due	12/07/2026		
Fuel Type	Hybrid Electric				

Type 2 charging cable
Hole in carpet in boot

Tyres

NSF	MICHELIN	4.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	4.0mm
OSR	MICHELIN	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable drivers seat
- Front parking sensor
- PAS
- Digital radio
- Opening panoramic glass roof
- Electrically adjustable passenger seat
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Folding rear seats
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Leather seat trim
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels

Photos

AU23 PFJ

AU23 PFJ

HYUNDAI

Fri 13/03
9:39 AM
DAB/FM
Capital XTRA
VOL −
VOL +
MAP
NAV
<SEEK
TRACK>
RADIO
MEDIA
SETUP
SYNC
23.0
23.0
AUTO
A/C

9:39 AM
Battery
17 %
EV range
0 mi
Nearby stations
0.3 mi
GenesPoint
Search stations
VOL −
VOL +
MAP
NAV
<SEEK
TRACK>
RADIO
MEDIA
SETUP
SYNC
23.0
23.0
AUTO
A/C

9:40 AM
VOL −
VOL +
MAP
NAV
<SEEK
TRACK>
RADIO
MEDIA
SETUP
SYNC
23.0
23.0
AUTO
A/C

0 MPH
0
25
50
75
167 MPG
ECO
29524 mi

Condition Check



Damage Photos

1: Wing osf
Scratched
Over 25mm Not Thru Paint

2: Door osf
Chipped
1 To 5

3: Door osf
Chipped
Edge Chip

4: Door osr
Scratched
Over 25mm Not Thru Paint

5: Door osr
Scratched
UpTo 25mm Thru Paint

6: Qtr Panel osr
Scratched
UpTo 25mm Not Thru Paint

7: Door nsr
Scratched
Over 25mm Not Thru Paint

8: Door nsf
Chipped
Edge Chip

9: Door nsf
Scratched
Over 25mm Not Thru Paint

10: Wing nsf
Scratched
Over 25mm Not Thru Paint

11: Bumper Front
Scratched
Over 25mm Not Thru Paint

12: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm

13: Qtr Panel osr
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		