46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GV19RAU

Kia Stonic 1.0T GDi 3 5dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	04/05/2019	**Body Style**	Hatchback	**Last service miles**	61,135
Year	2019	**Keys**	2	**MOT Due**	27/02/2027
Mileage	82,718 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
		Service documents	Service Book	**Gears**	6
Fuel Type	Petrol	**Number of stamps**	6	**Doors**	5
Colour	WHITE	**Last service date**	05/02/2025		
VIN	KNAD6811LK6273676				

£100 ADDITIONAL FEE
Last service 05/02/2025 at 61,135 miles- 6 main dealer services. Book Service overdue message displayed

Tyres

NSF	GT RADIAL	6.0mm
NSR	BUDGET	6.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	6.0mm
Spare		

Features

- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear parking sensor
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Park assist camera
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos

GV15 RAU

Turbo GDI

SEEK
TRACK
SETUP
AUTO
A/C
OFF

SEEK
TRACK
SETUP
AUTO
22.0°C
A/C

15:04
DAB/FM
AM
Menu
DAB
BBC Radio1Anthms
Now Playing: yes, and? by Ariana Grande
Favourites
List
Scan
TA
RADIO
MEDIA
SEEK
TRACK
NAV
SETUP



Condition Check



Damage Photos

1: Seat Base Cover osf
Scuffed
Over 25mm

2: Carpets Front
Holed
Over 3mm

3: Bonnet
Chipped
1 To 5

4: Bumper Front
Chipped
Multiple Chips

5: Wheel nsf
Scratched
Over 50mm

6: Wing nsf
Chipped
1 To 5

7: Door nsr
Chipped
1 To 5

8: Wheel nsr
Scratched
Over 50mm

9: Wheel osr
Scratched
Over 50mm

10: Bumper Rear
Scratched
Up To 25mm Thru Paint

11: Door osr
Scratched
Over 25mm Thru Paint

12: A Post os
Dented
Between 10mm + 30mm

13: Door osf
Dented
Over 30mm

14: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK