46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

KS64DHY

Nissan Qashqai 1.2 DiG-T Acenta Premium 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	01/01/2015	**Body Style**	Hatchback	**Last service miles**	76,869
Year	2015	**Keys**	2	**MOT Due**	10/05/2027
Mileage	77,260 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	Petrol	**Service documents**	Service Book	**Gears**	6
Colour	BLACK	**Number of stamps**	10	**Doors**	5
VIN	SJNFEAJ11U1246130	**Last service date**	16/04/2026		

Last service 16/04/2026 at 76,869 miles- 10 services (2 main dealer) Book and print

Tyres

NSF	NEXEN	6.0mm
NSR	BUDGET	5.0mm
OSF	NEXEN	6.0mm
OSR	BUDGET	5.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Digital radio
- Fixed panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos

UK



Heart
14:30
Menu
ENTER
AUTO
ON/OFF
DUAL

40
20
217
77260miles

Condition Check



Damage Photos

1: Bonnet
Scratched
Over 25mm Thru Paint

2: Other
N/A
N/A

3: Wheel nsf
Scratched
Over 50mm

4: Wing nsf
Chipped
1 To 5

5: Wing Front Arch Extension ns
Scuffed (Unpainted)
UpTo 100mm

6: Door nsf
Dented
Between 10mm + 30mm

7: Door nsf
Chipped
1 To 5

8: Door nsr
Dented
Over 30mm

9: Door nsr
Chipped
1 To 5

10: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint

11: Bumper Rear
Scratched
25 to 100mm Thru Paint

12: Qtr Panel osr
Scratched
Over 25mm Thru Paint

13: Door osr
Dented
Over 30mm

14: Wheel osr
Scratched
Up To 50mm

15: Door osf
Dented
Between 10mm + 30mm

16: Door osf
Scratched
UpTo 25mm Thru Paint

17: Wing osf
Dented
With Paint Damage

18: Wheel osf
Scratched
Over 50mm

19: Screen Front
Chipped
UpTo 10mm

20: Lamp osr
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		

Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		