

VEHICLE INSPECTION REPORT

LD60XZM

MINI HATCHBACK 1.6 Cooper [122] 3dr

Inspection Vehicle

VAT Margin
V5 Present



Details

13/12/2010	Body Style	Hatchback	MOT Due	06/01/2026
2010	Keys	2	CAP Clean	£1,250.00
90,735 Miles Warranted	Service history	Yes	CAP Average	£850.00
Petrol	Number of stamps	7	CAP Below	£450.00
Red	Last service date	25/02/2023	Gearbox	MANUAL
WMWSU32020TY97331	Last service miles	73,430	Doors	3
	2010 90,735 Miles Warranted Petrol Red	2010 Keys 90,735 Miles Warranted Service history Petrol Number of stamps	2010 Keys 2 90,735 Miles Warranted Service history Yes Petrol Number of stamps 7 Red Last service date 25/02/2023	2010 Keys 2 CAP Clean 90,735 Miles Warranted Service history Yes CAP Average Petrol Number of stamps 7 CAP Below Red Last service date 25/02/2023 Gearbox

£65 ADDITIONAL FEE. Last Service - 25.02.2023 at 73430 miles (7 services) Gear Stick knob broken.

Tyres

NSF

NSR

OSF OSR

Spare

Photos



















