



VEHICLE INSPECTION REPORT

NA61SSO

Toyota Verso 1.6 V-matic TR Pan Rf 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	26/10/2011	Keys	2	CAP Clean	£2,075.00
Year	2011	Service history	Yes	CAP Average	£1,650.00
Mileage	135,308 Miles Warranted	Service documents	Service Book	CAP Below	£1,275.00
Fuel Type	Petrol	Number of stamps	12	Gearbox	MANUAL
Colour	SILVER	Last service date	31/05/2024	Gears	6
VIN	NMTDE26R60R015702	Last service miles	128,619		
Body Style	MPV	MOT Due	13/07/2025		

£65 ADDITIONAL FEE

Last Service - 31.05.2024 at 128619 miles (12 services)


Tyres

NSF	TRIANGLE	4.0mm
NSR	HANKOOK	4.0mm
OSF	TRIANGLE	4.0mm
OSR	MICHELIN	3.0mm
Spare		

Features

- Rear wiper
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Central locking
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels

Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wheel osr
Scratched
Over 50mm



3: Bumper Rear
Scratched
25 to 100mm Thru Paint



4: Wheel nsr
Scratched
Over 50mm



5: Door nsr
Dented
2 Or Less UpTo 10mm



6: Wing nsf
Dented
With Paint Damage



7: Wheel nsf
Scratched
Over 50mm



8: Bumper Front
Poor Previous Repair
Paint Flake



9: Bonnet
Chipped
Multiple Chips

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK