



Vehicle Inspection Report

Date Inspected: 31/01/2025 17:50

LS64OLO Reg:

VIN: VF1JZ110651517673 NAMA Grading



Grade

Appraised By: Eastbourne Car Auctions

Genera	ΙГ)ല	ŀai	l۹
Ochlora	_		Lai	1

RENAULT Make Model SCENIC D-QUE TT

ENERGY TC - 1198cc

Mileage 88,798 miles

Body Type

Fuel Type Transmission

Gears

MPV Petrol

Manual

Colour

Doors

Year of MFR

Interior Condition

Upholstery Average

Black 2014

5

Date First Reg 30/09/2014 Miscellaneous

V5 Location Here MOT Location Here

MOT Expiry 29/09/2025

No. Keys

Tyres & Wheels

OSF Depth NSF Depth

OSR Depth

NSR Depth

5 mm 5 mm

5 mm

Alloys That Need 5 mm

Refurb Tools

Alloys

Spare

Yes

4

No

Steel

Parcel

Shelf

Seats

Carpets

Odour

Comments drivers seat torn and other seats heavily

Average

Poor

No

worn

Service History

Service Yes History

Stamps

Extras

Metallic Paint Air Conditioning Stereo **Keyless Entry Phone Kit**

Yes **Central Locking** Sun Roof Yes Sat Nav Radio Yes **Towbar** No **Drv Airbag**

Yes Interior **Elec Windows** No No Cruise

No

Number of Seats Yes **Reversing Camera** Half Leather 4

No 5 No **Electric Seats Heated Seats**

Xenons **Parking Sensors**

EML No

No

No

No

No

Damage Assessment



Seat Base Cover osf

Torn

Over 3mm

Replace



Bumper Rear

Poor Previous Repair

Poor Paint

Refinish



Boot Lid

Dented

Over 30mm

Repair and Refinish

Door osf

Chipped

Multiple

Chips

Refinish



Qtr Panel osr

Scratched

Over 25mm Thru Paint

Refinish

Wing osf

Scratched

25mm Not

Thru Paint

Machine Polish

Over



Door osr

Dented

With Paint Damage

Repair and Refinish



Chipped

1 To 5

Smart Repair



Bumper Front

Scratched

Over 100mm Thru Paint

Refinish



Bonnet

Chipped

1 To 5

Smart Repair



Wing nsf

Scratched

Over 25mm Not Thru Paint

Machine Polish



Door nsf

Dented

Over 30mm

Repair and Refinish



Door nsr

Poor Previous Repair

Poor Paint

Refinish

Qtr Panel nsr

Dented

Over 30mm

Repair and Refinish



Qtr Panel nsr

Poor Previous Repair

Poor Paint

Refinish

Damage Lines

Qtr Panel nsr

Condition Severity Repair Component Seat Base Cover osf Torn Over 3mm Replace **Bumper Rear** Poor Previous Repair Poor Paint Refinish **Boot Lid** Dented Over 30mm Repair and Refinish


Qtr Panel osr Scratched Over 25mm Thru Paint Refinish Dented Door osr With Paint Damage Repair and Refinish Refinish Door osf Chipped Multiple Chips Scratched Machine Polish Wing osf Over 25mm Not Thru Paint Wing osf Chipped 1 To 5 Smart Repair **Bumper Front** Scratched Over 100mm Thru Paint Refinish **Bonnet** Chipped 1 To 5 Smart Repair

Wing nsf Scratched Over 25mm Not Thru Paint Machine Polish
Door nsf Dented Over 30mm Repair and Refinish

Over 30mm

Door nsr Poor Previous Repair Poor Paint Refinish

Qtr Panel nsr Poor Previous Repair Poor Paint Refinish



Dented

Splat Key

S2

Scratch/Paint defect 30-100mm

Repair and Refinish

S

Scratch/Paint defect 100m +

D2

Dent/damage 30-100mm

C2

Multiple Chips

PP

Poor Previous

Comments

£100 ADDITIONAL FEE. Last Service - 26/09/2022 at 62,888 miles (8 services (7 main dealer))

satnav screen broken. intermittent eml

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.