

Vehicle Inspection Report

Date Inspected: 25/04/2025 09:48

Reg: GF14ZVM

VIN: WF0EXXGBBEEJ43649



Appraised By: Eastbourne Car Auctions

General I	Details						Miscella	aneous	
Make Model Mileage			Body Type Fuel Type Transmission Gears	Hatchbac Diesel Manual 6	Doors Colour Year of MFR Date First Reg	5 Silver 2014 02/05/2	V5 Loc No. Ke		
Tyres & Wheels					Interior Condit	Interior Condition		Service History	
OSF Der NSF Der OSR Der NSR Der	oth pth	5 mm 5 mm 6 mm 6 mm	Alloys Alloys That Need Refurb Tools Spare	Ye: 4 Ye: Ste	Carpets Upholstery Seats Parcel Shelf Odour	Avera Avera Avera Yes No	ige Hist	-	
Extras									
Metallic Air Conc Stereo Keyless Phone k	ditioning Entry	Yes Yes Radio No Yes	Central Locking Sun Roof Sat Nav Towbar Drv Airbag	Yes No Built In No Yes	nterior lec Windows cruise lumber of Seats reversing Camera	Cloth 4 Yes 5 No	Electric Seats Heated Seats Xenons Parking Sensors EML	No No Front & Rear No	

Damage Assessment





Qtr Panel nsr Dented

Door osf

Chipped

Smart

Repair

Edge Chip

2 Or Less UpTo 10mm

Smart Repair



Bonnet Chipped

Multiple Chips Refinish

Qtr Panel osr

Scratched

Over 25mm Not Thru Paint

Machine

Wing nsf

Scratched

25mm Not

Thru Paint

Machine

Polish

Over

Polish



Bumper Rear

Scratched

Over 100mm Thru Paint

Refinish

0

Bumper Front


Chipped

Multiple Chips

Smart Repair

Damage Lines

Component Condition Severity Repair Door osf Chipped Edge Chip Smart Repair Qtr Panel osr Scratched Over 25mm Not Thru Paint Machine Polish Bumper Rear Scratched Over 100mm Thru Paint Refinish Dented 2 Or Less UpTo 10mm Qtr Panel nsr Smart Repair Machine Polish Over 25mm Not Thru Paint Wing nsf Scratched **Bumper Front** Chipped **Multiple Chips** Smart Repair Chipped **Multiple Chips** Refinish Bonnet



Comments

£65 ADDITIONAL FEE

non runner car doesnt start,engine service now message on dash

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.