

Vehicle Inspection Report

Date Inspected: 22/04/2025 14:11

Reg: GU71XGD

VIN: JSAAZCC3S00501514

NAMA Grading



Grade

1

Appraised By: Eastbourne Car Auctions

General Details

Make	SUZUKI	Body Type	Hatchback	Doors	5
Model	SWIFT SPORT BOOSTERJET MH - 1373cc	Fuel Type	Hybrid	Colour	Blue
Mileage	18,278 miles	Transmission	Manual	Year of MFR	2021
		Gears	6	Date First Reg	07/09/2021

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	06/09/2025
No. Keys	2

Tyres & Wheels

OSF Depth	7 mm	Alloys	Yes
NSF Depth	7 mm	Alloys That Need Refurb	4
OSR Depth	5 mm	Tools	No
NSR Depth	5 mm	Spare	Inflation Kit

Interior Condition






Carpets	Good
Upholstery	Good
Seats	Good
Parcel Shelf	Yes
Odour	No

Service History

Service History
Stamps


Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	Built In	Cruise	No	Xenons	No
Keyless Entry	Yes	Towbar	No	Number of Seats	5	Parking Sensors	Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

Damage Assessment				
	Wing osf		Bumper Rear	Door nsr
	Chipped 1 To 5 Smart Repair		Scratched Over 25mm Not Thru Paint Machine Polish	Scratched Over 25mm Not Thru Paint Machine Polish
	Door nsf		Door nsf	Wing nsf
	Scratched Over 25mm Not Thru Paint Machine Polish		Chipped 1 To 5 Smart Repair	Scratched Over 25mm Not Thru Paint Machine Polish
	Bonnet	Screen Front		
	Chipped 1 To 5 Smart Repair	Chipped UpTo 10mm Smart Repair		

Damage Lines			
Component	Condition	Severity	Repair
Wing osf	Chipped	1 To 5	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bonnet	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair

Vehicle Splat



Splat Key

C1

Single Chip

C2

Multiple Chips

Comments

£65 ADDITIONAL FEE. Last Service - 30/08/2024 at 14,427 miles (4 main dealer services)

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.