

### Vehicle Inspection Report

Date Inspected: 14/02/2025 12:49

**Reg:** KD19FBG

**VIN:** SJNFFAJ11U2603750

### NAMA Grading



Grade

1

Appraised By: Eastbourne Car Auctions

### General Details

<b>Make</b>	NISSAN	<b>Body Type</b>	Hatchback	<b>Doors</b>	5
<b>Model</b>	QASHQAI N-MOTION DIG-T - 1332cc	<b>Fuel Type</b>	Petrol	<b>Colour</b>	Silver
<b>Mileage</b>	32,486 miles	<b>Transmission</b>	Manual	<b>Year of MFR</b>	2019
		<b>Gears</b>	6	<b>Date First Reg</b>	28/06/2019

### Miscellaneous

<b>V5 Location</b>	Here
<b>MOT Location</b>	Here
<b>MOT Expiry</b>	21/07/2025
<b>No. Keys</b>	2

### Tyres & Wheels

<b>OSF Depth</b>	5 mm	<b>Alloys</b>	Yes
<b>NSF Depth</b>	5 mm	<b>Alloys That Need Refurb</b>	4
<b>OSR Depth</b>	6 mm	<b>Tools</b>	No
<b>NSR Depth</b>	7 mm	<b>Spare</b>	Inflation Kit

### Interior Condition






<b>Carpets</b>	Good
<b>Upholstery</b>	Good
<b>Seats</b>	Good
<b>Parcel Shelf</b>	Yes
<b>Odour</b>	No

### Service History

**Service History**  
Stamps


### Extras

<b>Metallic Paint</b>	Yes	<b>Central Locking</b>	Yes	<b>Interior</b>	Cloth	<b>Electric Seats</b>	No
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	Yes	<b>Elec Windows</b>	4	<b>Heated Seats</b>	No
<b>Stereo</b>	Radio	<b>Sat Nav</b>	Built In	<b>Cruise</b>	Yes	<b>Xenons</b>	No
<b>Keyless Entry</b>	Yes	<b>Towbar</b>	No	<b>Number of Seats</b>	5	<b>Parking Sensors</b>	Front & Rear
<b>Phone Kit</b>	Yes	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	Yes	<b>EML</b>	No

Damage Assessment					
	<b>Door osf</b>		<b>Door osr</b>		<b>Bumper Rear</b>
	Chipped		Dented		Chipped
	1 To 5		2 Or Less UpTo 10mm		1 To 5
	Smart Repair		Smart Repair		Smart Repair
	<b>Qtr Panel nsr</b>		<b>Door nsr</b>		<b>Door nsr</b>
	Scratched		Chipped		Scratched
	Over 25mm Not Thru Paint		1 To 5		Over 25mm Not Thru Paint
	Machine Polish		Smart Repair		Machine Polish
	<b>Door nsf</b>		<b>Door Mirror Assy nsf</b>		<b>Bonnet</b>
	Scratched		Scratched (Painted)		Chipped
	Over 25mm Not Thru Paint		Over 25mm Not Thru Paint		1 To 5
	Machine Polish		Machine Polish		Smart Repair

Damage Lines			
Component	Condition	Severity	Repair
Door osf	Chipped	1 To 5	Smart Repair
Door osr	Dented	2 Or Less UpTo 10mm	Smart Repair
Bumper Rear	Chipped	1 To 5	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Chipped	1 To 5	Smart Repair
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door Mirror Assy nsf	Scratched (Painted)	Over 25mm Not Thru Paint	Machine Polish
Bonnet	Chipped	1 To 5	Smart Repair

## Vehicle Splat



## Splat Key

### D1

Dent/damage under 30mm

### C1

Single Chip

### C2

Multiple Chips

## Comments

£100 ADDITIONAL FEE. Last Service - 04/03/2024 at 28,516 miles (4 services (3 main dealer))

**No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.**