

Vehicle Inspection Report

Date Inspected: 18/03/2025 11:48

Reg: LY64RWF


VIN: W0L0MAP08F6015121



Appraised By: Eastbourne Car Auctions


General Details						Miscellaneous	
Make VAUXHAL Model ADAM JA Mileage 68376 mi	M - 1398cc	Body Type Fuel Type Transmissior Gears	Hatchback Petrol Manual 5	Doors Colour Year of MFR Date First Reg	3 Yellow 2014 24/12/2014	V5 Location No. Keys	1
Tyres & Wheels				Interior Conditi	on	Service History	
OSF Depth NSF Depth OSR Depth NSR Depth	5 mm 7 mm 7 mm 7 mm	Alloys Yes Tools No Spare Infl		Carpets Upholstery Seats Parcel Shelf Odour	Average Average Average Yes No	Service No History Stamps	
Extras							
Metallic Paint	No	Central Locki	ng Yes	Interior	Leather	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	2 Yes	Heated Seats Xenons	No No
Stereo	Radio	Sat Nav	No	No Cruise			
Keyless Entry	No	Towbar	No	Number of Seats	4	Parking Sensors	No
, ,	Phone Kit Yes			Reversing Camera	No	EML	

Damage Assessment



Damage Lines

Component	Condition	Severity	Repair
Wing osf	Chipped	1 To 5	Smart Repair
Door osf	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Scratched	UpTo 25mm Thru Paint	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	Edge Chip	Smart Repair
Bumper Front	Chipped	Multiple Chips	Smart Repair
Bonnet	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair



Comments

intermittent starting,speedo doesn't work

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.