

Vehicle Inspection Report

Date Inspected: 18/03/2025 09:50

Reg: GF19LWN

VIN: VSSZZZ5FZK6550603




Appraised By: Eastbourne Car Auctions

General Details								Miscellaneou	us	
Make SEAT Model ATECA > TSI EVO Mileage 100,454	S - 1498cc	Body Type Fuel Type Transmission	Hatch Petro Auto	aback Doors I Colour Year of MFI Date First R	R 2	Drange 1019 8/03/2019		V5 Location MOT Locat MOT Expiry No. Keys	ion Here	
Tyres & Wheels				Interior Co	Interior Condition			Service History		
OSF Depth NSF Depth OSR Depth NSR Depth	6 mm 6 mm 7 mm 6 mm	Alloys Alloys That Need Refurb Tools Spare	No	Upholste Seats	-	Average Average Average Yes No		Service Y History Stamps	Yes	
Extras			Kit							
Metallic Paint	Yes	Central Locking	Yes	Interior	Half I	_eather E	Electric	Seats	No	
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	ŀ	leated	Seats	No	
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	>	(enons		No	
	N.L.	Towbar	No	Number of Seats	5	F	Parking	Sensors	Front & Rear	
Keyless Entry	No	lowbal								

Damage Assessment









Screen Front

Chipped

UpTo 10mm Smart Repair

Bumper Front Chipped 1 To 5 Smart Repair

Door nsf

Door

UpTo

25mm

Thru Paint Smart Repair

Mirror

Dented Between 10mm + 30mm

Smart Repair



UpTo 10mm

Smart

Repair



Door Mirror Assy nsf

Broken

Needs Replaced

Replace

Damage Lines


Component Door Mirror Assy nsf Bonnet Screen Front **Bumper Front** Door nsr Door Mirror Assy nsf Door nsf

Condition Scratched (Painted) Chipped Chipped Chipped Dented Broken Dented

Severity UpTo 25mm Thru Paint 1 To 5 UpTo 10mm 1 To 5 Over 2 UpTo 10mm Replace Between 10mm + 30mm

Repair

Smart Repair Smart Repair Smart Repair Smart Repair Smart Repair Replace Smart Repair



Comments

£65 ADDITIONAL FEE Last Service - 29/05/2024 at 88,476 miles (9 MAIN DEALER SERVICES)

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.