

VEHICLE INSPECTION REPORT

AO14XFV

Nissan Note 1.2 DiG-S Acenta Premium 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
4

Details

Reg. date	09/06/2014	Colour	SILVER	MOT Due	08/12/2026
Year	2014	VIN	SJNTBAE12U1059205	Gearbox	CVT
Mileage	83,317 Miles Warranted	Body Style	MPV	Gears	5
Fuel Type	Petrol	Keys	2		

Tyres


NSF	RAPID	6.0mm
NSR	RAPID	6.0mm
OSF	RAPID	6.0mm
OSR	LAUFENN	6.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Navigation system
- Digital radio
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Chipped
1 To 5



7: Sill ns
Dented
With Paint Damage



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



10: Bumper Rear
Cracked
UpTo 25mm



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Door osr
Scratched
Over 25mm Thru Paint




13: Door nsf
Dented
Over 30mm



14: Wheel osf
Scratched
Over 50mm



15: Wing of
Chipped
1 To 5



16: Screen Front
Chipped
Up To 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK