



# VEHICLE INSPECTION REPORT

**GX16MLZ**

## Land Rover Discovery 3.0 SDV6 SE Tech 5dr Auto

nama  
 GRADE  
**2**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	02/03/2016	Body Style	Estate	Last service miles	61,363
Year	2016	Keys	2	MOT Due	16/02/2027
Mileage	94,723 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	8
Colour	BLACK	Number of stamps	7		
VIN	SALLAAAG5GA798476	Last service date	22/02/2023		

Timing belt replaced 22/02/2023 at 61,363 miles

Last service 22/02/2023 at 61,363 miles- 7 services (2 main dealer) Book and print Noisy air suspension pump

### Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	5.0mm
Spare		

### Features


- Bluetooth connection
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

### Photos





## Condition Check



## Damage Photos



1: Wing osf  
Chipped  
1 To 5



2: Wing Front Arch Extension os  
Scratched (Painted)  
Over 25mm Thru Paint



3: Door osf  
Chipped  
1 To 5



4: Door osf  
Chipped  
Edge Chip



5: Door osr  
Chipped  
Edge Chip



6: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



7: Door Moulding nsr  
Scratched (Painted)  
Over 25mm Thru Paint



8: Door Mirror Assy nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint



9: Wing Front Arch Extension ns  
Scratched (Painted)  
Over 25mm Thru Paint



10: Bumper Front  
Chipped  
1 To 5



11: Bonnet  
Chipped  
1 To 5



12: Roof  
Chipped  
1 To 5



13: Screen Front  
Chipped  
Up To 10mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK