



VEHICLE INSPECTION REPORT

LD10YTG

Volkswagen Golf 1.4 TSI SE 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	31/03/2010	Body Style	Hatchback	Last service miles	59,538
Year	2010	Keys	2	MOT Due	10/02/2027
Mileage	60,594 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	11	Doors	5
VIN	WVVZZZ1KZAW347616	Last service date	28/01/2026		

£90 ADDITIONAL FEE

LAST SERVICE 28/01/2026 @ 59538 MILES (11 SERVICES, 1 MAIN DEALER) Possible gearbox whine
 Engine slightly knocking on idle

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Heated front seat
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint



2: Door osf
Chipped
1 To 5



3: Qtr Panel osr
Chipped
1 To 5



4: Bumper Rear
Chipped
1 To 5



5: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



6: Door nsr
Dented
2 Or Less UpTo 10mm




7: Door nsf
Chipped
1 To 5



8: Bumper Front
Chipped
Multiple Chips



9: Bonnet
Chipped
1 To 5



10: Roof
Dented
Over 30mm



11: Tailgate
Scratched
Up To 25mm Thru Paint



12: Other
N/A
N/A

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK