

VEHICLE INSPECTION REPORT

GU61FNP

Toyota Yaris 1.0 VVT-i T Spirit Nav 3dr

nama
 GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	02/09/2011	Body Style	Hatchback	Last service miles	73,183
Year	2011	Keys	2	MOT Due	18/10/2026
Mileage	80,508 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	6	Doors	3
VIN	VNKJG96330A331100	Last service date	23/09/2024		

Last Service - 23.09.2024 at 73183 miles (6 services) Reverse camera does not work

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Solid Paint
- Central locking
- Park assist camera
- Radio/CD
- Climate control
- ABS
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



2: Door osf
Chipped
1 To 5



3: Other
N/A
N/A



4: Other
N/A
N/A



5: Door nsf
Chipped
1 To 5



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Wing nsf
Chipped
1 To 5




8: Wheel nsf
Scratched
Over 50mm



9: Bumper Front
 Scratched
 25 to 100mm Thru Paint



10: Bonnet
 Chipped
 1 To 5



11: Screen Front
 Chipped
 UpTo 10mm



12: A Post os
 Chipped
 1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK