



VEHICLE INSPECTION REPORT

GL09YXT

Ford Focus 1.6 Titanium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	20/08/2009	Body Style	Hatchback	Last service miles	63,641
Year	2009	Keys	2	MOT Due	11/10/2026
Mileage	95,992 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	GREY	Number of stamps	1	Doors	5
VIN	WF0PXXWDP9A10252	Last service date	12/10/2017		

£100 ADDITIONAL FEE.

LAST SERVICE 12/10/2017 @ 63,641 MILES (1 SERVICE) Steering noisy in full lock

Tyres

NSF	LAUFENN	3.0mm
NSR	YOKOHAMA	4.0mm
OSF	LAUFENN	4.0mm
OSR	YOKOHAMA	4.0mm

Spare

Features


- Cruise control
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Chipped
Edge Chip



6: Door osr
Scratched
Up To 25mm Thru Paint



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Wheel osr
Scratched
Over 50mm



9: Door osr
Chipped
1 To 5



10: Door osf
Chipped
Multiple Chips



11: Wheel osf
Scratched
Over 50mm



12: Wing osf
Scratched
UpTo 25mm Thru Paint



13: Door osf
Dented
Over 30mm



14: Screen Front
Cracked
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	Fault