

VEHICLE INSPECTION REPORT

LB13LNE

Ford Focus 1.6 TDCi 115 Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	31/07/2013	Body Style	Hatchback	Last service miles	119,125
Year	2013	Keys	2	MOT Due	28/12/2026
Mileage	134,414 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	4	Doors	5
VIN	WF0KXXGCBKDR05762	Last service date	26/05/2023		

Last service 26/05/2023 at 119,125 miles- 4 services
Cambelt replaced 20/12/2017 mileage not recorded

Tyres


NSF	BUDGET	3.0mm
NSR	TOYO	5.0mm
OSF	BUDGET	3.0mm
OSR	TOYO	5.0mm
Spare		

Features


- Bluetooth connection
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Metallic Paint
- Traction control
- Alloy wheels
- Telephone
- Air conditioning
- ABS
- Central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm




2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Scratched
UpTo 25mm Thru Paint



6: Wheel osr
Corroded
Light



7: Bumper Rear
Chipped
Multiple Chips



8: Tailgate
Chipped
1 To 5



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Chipped
1 To 5



11: Door nsf
Chipped
Edge Chip




12: Wheel nsf
Scratched
Up To 50mm



13: Bumper Front
Scratched
Over 100mm Thru Paint



14: Bonnet
Poor Previous Repair
Paint Flake



15: Screen Front
Chipped
UpTo 10mm



16: Roof
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK