



# VEHICLE INSPECTION REPORT

**OE65VOY**

## Volkswagen Golf 1.6 TDI 110 Match 5dr DSG

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	06/01/2016	Body Style	Hatchback	Last service miles	123,207
Year	2016	Keys	2	MOT Due	05/01/2027
Mileage	139,799 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Service Book	Gears	7
Colour	SILVER	Number of stamps	12	Doors	5
VIN	WVVZZZAUZGW053881	Last service date	09/12/2024		

£90 ADDITIONAL FEE

Last service 09/12/2024 at 123,207 miles- 12 main dealer services. Book and print Rear bumper out of line

### Tyres

NSF	NEXEN	5.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	4.0mm
OSR	NEXEN	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Telephone
- Electric sunroof
- Rear electric windows
- Drivers airbag
- Central locking
- Park assist camera
- Radio/CD
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Wing osf  
Chipped  
1 To 5



2: Door osf  
Dented  
Between 10mm + 30mm



3: Door osf  
Chipped  
Edge Chip



4: Qtr Panel osr  
Chipped  
1 To 5



5: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



6: Qtr Panel nsr  
Dented  
Over 30mm



7: Wheel nsr  
Scratched  
Over 50mm



8: Door nsr  
Chipped  
1 To 5



9: Door nsf  
Chipped  
1 To 5



10: Bumper Front  
Poor Previous Repair  
Paint Flake



11: Bonnet  
Chipped  
Multiple Chips



12: Screen Front  
Chipped  
UpTo 10mm



13: Other  
N/A  
N/A

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK