



VEHICLE INSPECTION REPORT

GY10CVM

Citroen Berlingo Multispace 1.6 HDi 90 XTR 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	24/03/2010	Keys	2	CAP Clean	£1,600.00
Year	2010	Service history	Yes	CAP Average	£1,200.00
Mileage	117,538 Miles Warranted	Service documents	Service Book	CAP Below	£800.00
Fuel Type	Diesel	Number of stamps	4	Gearbox	MANUAL
Colour	BLUE	Last service date	09/05/2019	Gears	5
VIN	VF77J9HXCAJ583949	Last service miles	73,886		
Body Style	MPV	MOT Due	10/03/2026		

Last Service - 09.05.2019 at 73886 miles (4 services (3 main dealer))
EGR Fault.

Tyres

NSF	LAUFENN	5.0mm
NSR	LAUFENN	5.0mm
OSF	LAUFENN	5.0mm
OSR	LAUFENN	5.0mm
Spare		

Features


- Cruise control
- Audio remote control
- Climate control
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Radio/CD
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Steel wheels

Photos





Condition Check



Damage Photos




1: Bonnet
Chipped
1 To 5



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Wing osf
Chipped
1 To 5



4: Wing osf
Scratched
Over 25mm Not Thru Paint



5: Door osf
Chipped
1 To 5



6: Door osf
Scratched
Over 25mm Not Thru Paint




7: Door osf
Scratched
Over 25mm Thru Paint



8: Qtr Panel osr
Dented
With Paint Damage



9: Boot Lid
Poor Previous Repair
Poor Paint



10: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



11: Qtr Panel nsr
Dented
With Paint Damage



12: Door nsr
Dented
With Paint Damage



13: Door nsf
Dented
With Paint Damage



14: Wing nsf
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK