



VEHICLE INSPECTION REPORT

HK09FNZ

Kia Picanto 1.1 Chill 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/07/2009	Keys	2	CAP Clean	£630.00
Year	2009	Service history	Yes	CAP Average	£260.00
Mileage	64,543 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Petrol	Number of stamps	13	Gearbox	MANUAL
Colour	BLACK	Last service date	14/06/2024	Gears	5
VIN	KNABA24329T794048	Last service miles	61,624	Doors	5
Body Style	Hatchback	MOT Due	22/06/2025		

£100 ADDITIONAL FEE. Last Service: 14/06/2024 at 61624 miles. (13 services (6 main dealer)). Book & print.
Parcel shelf damaged

Tyres


NSF	RAPID	3.0mm
NSR	RAPID	3.0mm
OSF	BUDGET	4.0mm
OSR	RAPID	4.0mm
Spare		

Features


- PAS
- Climate control
- Solid Paint
- Remote central locking
- Rear wiper
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Radio/CD
- Front head restraints
- Passenger airbag
- Steel wheels
- Body coloured bumpers
- Rear headrests
- Central locking

Photos





Condition Check



Damage Photos




1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Door nsf
Dented
With Paint Damage



5: Door nsr
Dented
Over 30mm



6: Bumper Rear
Scratched
Over 100mm Thru Paint




7: Boot Lid
Rusted
UpTo 5mm



8: Qtr Panel osr
Chipped
1 To 5



9: Door osr
Chipped
Multiple Chips



10: Door osf
Dented
With Paint Damage



11: Wing osf
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK