



# VEHICLE INSPECTION REPORT

**LJ65JBE**

## Ford Grand C-Max 1.5 TDCi Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	04/12/2015	Body Style	MPV	CAP Clean	£4,075.00
Year	2015	Keys	1	CAP Average	£3,500.00
Mileage	91,195 Miles Warranted	Service history	Yes	CAP Below	£2,900.00
Fuel Type	Diesel	Service documents	Printout	Gearbox	MANUAL
Colour	WHITE	Last service date	03/02/2024	Gears	6
VIN	WF0WXXGCEWFS25723	MOT Due	22/01/2026		

£100 ADDITIONAL FEE Last service 03/02/2024 (2 SERVICES) MILEAGE AT LAST SERVICE UNAVAILABLE


### Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Bluetooth connection
- Radio/CD
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Wing osf  
Poor Previous Repair  
Poor Colour






3: Other  
N/A  
N/A



4: Door osr  
Chipped  
1 To 5



5: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



6: Bumper Rear  
Chipped  
Multiple Chips



7: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



8: Wheel nsf  
Scratched  
Over 50mm



9: Bonnet  
Chipped  
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK