



VEHICLE INSPECTION REPORT

LM15NEU

Fiat 500 1.2 Lounge 2dr Dualogic [Start Stop]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	02/07/2015	Body Style	Convertible	Last service miles	61,784
Year	2015	Keys	2	MOT Due	01/01/2027
Mileage	61,813 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	6		
VIN	ZFA312000J280440	Last service date	06/12/2025		

£90 ADDITIONAL FEE

Last service 06/12/2025 at 61,784 miles- 6 services Soft roof torn

Tyres


NSF	TRIANGLE	6.0mm
NSR	TRIANGLE	5.0mm
OSF	ROVELO	5.0mm
OSR	TRIANGLE	5.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Steering wheel mounted controls
- Air conditioning
- Steering wheel rake adjustment
- ABS
- Central locking
- Radio/CD
- Front electric windows
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Front head restraints
- Metallic Paint
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Scratched
Over 25mm Thru Paint



4: Qtr Panel osr
Scratched
Over 25mm Thru Paint



5: Wheel osr
Scratched
Over 50mm



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Door nsf
Chipped
Edge Chip




10: Sill ns
Dented
With Paint Damage



11: Wing nsf
Scratched
Over 25mm Thru Paint



12: Wheel nsf
Scratched
Over 50mm



13: Bumper Front
Scratched
Over 100mm Thru Paint



14: Front TowEye Cvr
Missing
Replace



15: Bonnet
Chipped
1 To 5



16: A Post os
Chipped
1 To 5



17: Screen Front
Chipped
UpTo 10mm



18: Other
N/A
N/A



19: Air Vents of
Damaged
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK