

# VEHICLE INSPECTION REPORT

**DE12WWF**

## Mini Convertible 1.6 One 2dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	17/04/2012	VIN	WMWZM320X0T131443	Last service date	02/01/2014
Year	2012	Body Style	Convertible	Last service miles	28,929
Mileage	101,163 Miles Warranted	Service history	Yes	MOT Due	08/04/2027
Fuel Type	Petrol	Service documents	Printout	Gearbox	MANUAL
Colour	WHITE	Number of stamps	1	Gears	6

Last service 02/01/2014 at 28,929 miles- 1 main dealer service

### Tyres

NSF	RADAR	6.0mm
NSR	RADAR	6.0mm
OSF	ZEETEX	7.0mm
OSR	RADAR	6.0mm
Spare		

### Features


- Bluetooth connection
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- PAS
- Electric door mirrors
- Front head restraints
- Steering wheel rake adjustment
- Isofix child seat anchor points
- Partial leather seat trim
- Rear parking sensor
- Air conditioning
- Height adjustable drivers seat
- Solid Paint
- Passenger airbag
- Alloy wheels
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Alarm

### Photos





## Condition Check



## Damage Photos



1: Qtr Panel osr  
Dented  
With Paint Damage



2: Door osf  
Scratched  
UpTo 25mm Not Thru Paint



3: Bonnet  
Dented  
2 Or Less UpTo 10mm



4: Bonnet  
Scratched  
Over 25mm Thru Paint



5: Bumper Front  
Scratched  
25 to 100mm Thru Paint



6: Door nsf  
Dented  
Between 10mm + 30mm



7: Qtr Panel nsr  
Scratched  
UpTo 25mm Thru Paint

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK