



# VEHICLE INSPECTION REPORT

**YP63TXX**

## Ford B-Max 1.0 EcoBoost Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	29/11/2013	VIN	WF0KXXERJKDR74325	Last service date	29/07/2025
Year	2013	Body Style	MPV	Last service miles	31,753
Mileage	33,565 Miles Warranted	Service history	Yes	MOT Due	14/08/2026
Fuel Type	Petrol	Service documents	Service Book	Gearbox	MANUAL
Colour	SILVER	Number of stamps	11	Gears	5

LAST SERVICE 29/07/2025 @ 31,753 MILES (11 SERVICES, ALL MAIN DEALER)  
 GEARBOX REPLACED 15/05/2026 @ 33,541 MILES

### Tyres

NSF	FALKEN	5.0mm
NSR	FALKEN	5.0mm
OSF	FALKEN	5.0mm
OSR	FALKEN	5.0mm


### Spare

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Alarm
- PAS
- Telephone
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Trip computer
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Tyre pressure monitor
- Alloy wheels

## Photos






## Condition Check



## Damage Photos



1: Door osf  
Scratched  
Over 25mm Thru Paint



2: Screen Front  
Chipped  
Over 10mm



3: Wheel osf  
Corroded  
Light



4: Bonnet  
Chipped  
Multiple Chips




5: Bumper Front  
Poor Previous Repair  
Poor Paint




6: Wing nsf  
Scratched  
Over 25mm Thru Paint



7: Wheel nsf  
Corroded  
Light



8: Roof  
Chipped  
1 To 5



9: Door nsf  
Scratched  
Over 25mm Thru Paint



10: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



11: Bumper Rear  
Chipped  
Multiple Chips



12: Other  
N/A  
N/A

**Interior**

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK