



VEHICLE INSPECTION REPORT

YK18OZZ

BMW 3 Series 320d M Sport 5dr Step Auto

nama
GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Photocopy

Details

Reg. date	31/07/2018	Body Style	Estate	Last service miles	80,338
Year	2018	Keys	2	MOT Due	28/02/2027
Mileage	98,185 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	8
Colour	GREY	Number of stamps	3		
VIN	WBA8H92000A691079	Last service date	03/10/2025		

LAST SERVICE 03/10/2025 @ 80,338 MILES (3 SERVICES)

Photocopy V5 Only

Tyres

NSF	HANKOOK	3.0mm
NSR	HANKOOK	5.0mm
OSF	HANKOOK	3.0mm
OSR	HANKOOK	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wheel osr
Corroded
Light



3: Qtr Panel osr
Poor Previous Repair
Poor Paint



4: Bumper Rear
Dented
With Paint Damage



5: Wheel nsr
Corroded
Light



6: Door nsr
Chipped
1 To 5



7: Wheel nsf
Corroded
Light



8: Bumper Front
Scratched
25 to 100mm Thru Paint



9: Bonnet
Chipped
1 To 5



10: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK