



VEHICLE INSPECTION REPORT

GU24ZBC

Volkswagen Golf 1.5 eTSI 150 R-Line 5dr DSG

nama
 GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	22/03/2024	Body Style	Hatchback	Last service miles	8,417
Year	2024	Keys	1	Gearbox	SEMI AUTO
Mileage	8,866 Miles Warranted	Service history	Yes	Gears	7
Fuel Type	Hybrid Electric	Service documents	Printout	Doors	5
Colour	SILVER	Number of stamps	1		
VIN	WVVZZZCD8RW181259	Last service date	18/03/2026		

£90 ADDITIONAL FEE

Last service 18/03/2026 at 8417 miles- 1 main dealer service

Tyres

NSF	BRIDGESTONE	6.0mm
NSR	BRIDGESTONE	6.0mm
OSF	BRIDGESTONE	6.0mm
OSR	BRIDGESTONE	Damaged
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Tyre osr
Damaged
Replace



2: Bonnet
Chipped
1 To 5



3: Headlamp nsf
Broken
Replace




4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



11: Wheel osf
Scratched
Over 50mm



12: Qtr Panel osf
Scratched
UpTo 25mm Thru Paint



13: Door osf
Chipped
Edge Chip



14: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK