



VEHICLE INSPECTION REPORT

RV67CMU

Nissan Qashqai 1.2 DiG-T Tekna 5dr

nama
 GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	21/09/2017	Body Style	Hatchback	Last service miles	60,872
Year	2017	Keys	2	MOT Due	22/07/2026
Mileage	66,699 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	6	Doors	5
VIN	SJNFEAJ11U2001112	Last service date	22/11/2025		

Last service 22/11/2025 at 60872 miles (6 services (4 main dealer). System fault on dash

Tyres


NSF	BUDGET	2.0mm
NSR	CONTINENTAL	4.0mm
OSF	BUDGET	3.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
1 To 5



3: Door osr
Poor Previous Repair
Poor Paint



4: Wheel osr
Corroded
Light



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Bumper Rear
Chipped
Multiple Chips



8: Door nsr
Dented
Over 30mm



9: Wheel nsf
Corroded
Light



10: Door nsf
Dented
Between 10mm + 30mm



11: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



12: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



13: Door nsf
Chipped
1 To 5



14: Wing nsf
Chipped
1 To 5



15: Wheel nsf
Scratched
Over 50mm



16: Bumper Front
Scratched
25 to 100mm Thru Paint



17: Bonnet
Chipped
1 To 5



18: Door Pad osf
Torn
Between 3mm + 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		