



VEHICLE INSPECTION REPORT

LD72OCU

Vauxhall Grandland 1.2 Turbo Ultimate 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	07/10/2022	Body Style	Hatchback	Last service miles	13,568
Year	2022	Keys	2	MOT Due	19/02/2027
Mileage	18,572 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	2	Doors	5
VIN	W0VZRHNS9N6832680	Last service date	09/04/2025		

£90 ADDITIONAL FEE.

Last service 09/04/2025 at 13568 miles (2 main dealer services). Service due message displayed

Tyres

NSF	MICHELIN	5.0mm
NSR	MICHELIN	2.0mm
OSF	GOODYEAR	5.0mm
OSR	MICHELIN	Damaged
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Partial leather seat trim
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear parking sensor
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Rippled Up To 30%



3: Wing nsf
Poor Previous Repair
Poor Paint



4: Door nsf
Dented
Between 10mm + 30mm



5: Door nsr
Dented
Between 10mm + 30mm



6: Door nsf
Poor Previous Repair
Poor Paint



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Tailgate
Scratched
Over 25mm Thru Paint



9: Door osr
Dented
Between 10mm + 30mm



10: Door osf
Scratched
Over 25mm Thru Paint



11: Wing osf
Scratched
UpTo 25mm Thru Paint



12: Roof
Scratched
Over 25mm Thru Paint



13: Tyre osr
Damaged
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK