



VEHICLE INSPECTION REPORT

KY07USP

Seat Leon 2.0 16V T FSI FR 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE 5

Details

Reg. date	01/03/2007	Body Style	Hatchback	MOT Due	06/03/2027
Year	2007	Keys	2	Gearbox	MANUAL
Mileage	100,206 Miles Warranted	Service history	Yes	Gears	6
Fuel Type	Petrol	Service documents	Printout	Doors	5
Colour	GREY	Number of stamps	2		
VIN	VSSZZZ1PZ7R029771	Last service date	06/02/2026		

last service 6/2/26 mileage not recorded (2 services)

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Rear wiper
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Cloth seat trim
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wing of
Hole
Over 10mm



2: Wheel of
Scratched
Over 50mm



3: Door osf
Poor Previous Repair
Poor Paint



4: Door osr
Poor Previous Repair
Poor Paint



5: Qtr Panel osr
Poor Previous Repair
Poor Paint



6: Wheel osr
Scratched
Over 50mm



7: Bumper Rear
Poor Previous Repair
Poor Paint



8: Tailgate
Poor Previous Repair
Poor Paint



9: Qtr Panel nsr
Poor Previous Repair
Poor Paint




10: Wheel nsr
Scratched
Over 50mm




11: Door nsr
Scratched
Over 25mm Thru Paint



12: Door nsf
Scratched
Over 25mm Thru Paint



13: Wing nsf
Hole
Over 10mm



14: Sill ns
Rusted
Over 5mm



15: Bumper Front
Cracked
Over 25mm



16: Bonnet
Chipped
1 To 5



17: C Post os
Poor Previous Repair
Poor Paint



18: Lamp osr
Broken
Replace



19: Lamp nsr
Broken
Replace



20: C Post ns
Poor Previous Repair
Poor Paint



21: Sill os
Rusted
Over 5mm

22: Seat Base Cover osf
Scuffed
UpTo 25mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK