



VEHICLE INSPECTION REPORT

DC65UFM

Land Rover Discovery Sport 2.0 TD4 180 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	18/01/2016	Body Style	Estate	MOT Due	23/10/2025
Year	2016	Keys	2	CAP Clean	£5,050.00
Mileage	91,863 Miles Warranted	Service history	Yes	CAP Average	£4,375.00
Fuel Type	Diesel	Number of stamps	7	CAP Below	£3,725.00
Colour	WHITE	Last service date	07/04/2025	Gearbox	MANUAL
VIN	SALCA2CN5GH587510	Last service miles	90,346	Gears	6

£100 ADDITIONAL FEE Engine vibration/rattle

Tyres

NSF	NEXEN	5.0mm
NSR	PIRELLI	3.0mm
OSF	NEXEN	5.0mm
OSR	PIRELLI	3.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Audio remote control
- Towbar
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Cruise control
- Rear parking sensor
- Digital radio
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bonnet
Scratched
Over 25mm Not Thru Paint



3: Bumper Front
Poor Previous Repair
Paint Flake



4: Wheel nsf
Scratched
Over 50mm




5: Door nsf
Dented
With Paint Damage



6: Door nsr
Dented
With Paint Damage



7: Wheel nsr
Scratched
Over 50mm




8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Bumper Rear
Scratched
Over 25mm Not Thru Paint



10: Boot Lid
Dented
Over 30mm




11: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Chipped
1 To 5



14: Door osr
Scratched
Over 25mm Not Thru Paint



15: Door osf
Chipped
1 To 5



16: Wheel osf
Scratched
Over 50mm



17: Screen Front
Chipped
UpTo 10mm



18: Other
N/A
N/A

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK