



VEHICLE INSPECTION REPORT

GY69HNU

Audi Q3 35 TFSI Edition 1 5dr

nama
GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	30/10/2019	Body Style	Estate	Last service miles	67,170
Year	2019	Keys	2	MOT Due	29/10/2026
Mileage	78,150 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLACK	Number of stamps	7		
VIN	WAUZZZF33L1027885	Last service date	10/10/2025		

£90 ADDITIONAL FEE

last service 10/10/25 @ 67,170 miles (7 main dealer) Breather pipe split see pictures

Tyres




NSF	HANKOOK	2.0mm
NSR	HANKOOK	2.0mm
OSF	HANKOOK	3.0mm
OSR	HANKOOK	2.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Heated front seat
- Telephone
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wing of
Chipped
1 To 5



2: Wheel of
Corroded
Light



3: Qtr Panel osr
Chipped
1 To 5



4: Door nsr
Dented
Over 30mm



5: Wheel nsf
Corroded
Light



6: Bonnet
Chipped
1 To 5



7: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK