



VEHICLE INSPECTION REPORT

GL11KYN

Skoda Yeti 1.8 TSI SE 4x4 5dr

nama
GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	21/07/2011	Body Style	Hatchback	Last service miles	74,111
Year	2011	Keys	2	MOT Due	18/02/2027
Mileage	75,283 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	WHITE	Number of stamps	13	Doors	5
VIN	TMBMB75L3C6011518	Last service date	02/02/2026		

£90 ADDITIONAL FEE

last service 2/2/26 @ 74,111 miles (13 services 3 main dealer) book
 clutch replaced on 4/11/25 @ 73,079 miles EPC light on
 Engine noisy when revved

Tyres

NSF	BUDGET	5.0mm
NSR	FALKEN	5.0mm
OSF	BUDGET	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Cruise control
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Solid Paint
- Traction control
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Wing of
Scratched
Up To 25mm Thru Paint



2: Wheel of
Scratched
Over 50mm



3: Door osf
Rusted
UpTo 5mm



4: Door osr
Rusted
Over 5mm



5: Qtr Panel osr
Rusted
UpTo 5mm



6: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



7: Badgedecal Rear
Missing
Replace



8: Wheel nsr
Scratched
Up To 50mm




9: Door nsr
Chipped
Multiple Chips



10: Door nsf
Rusted
Up To 5mm



11: Wheel nsf
Scratched
Up To 50mm



12: Bonnet
Poor Previous Repair
Paint Flake



13: Bumper Front
Scratched
Up To 25mm Thru Paint



14: Roof
Poor Previous Repair
Paint Flake

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK