

# VEHICLE INSPECTION REPORT

**GY65EAK**

## Citroen Dispatch 1000 1.6 HDi 90 H1 Van Enterprise

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	30/09/2015	Keys	2	CAP Clean	£2,425.00
Year	2015	Service history	Yes	CAP Average	£1,975.00
Mileage	89,295 Miles Warranted	Service documents	Service Book	CAP Below	£1,425.00
Fuel Type	Diesel	Number of stamps	1	Gearbox	MANUAL
Colour	GREY	Last service date	08/06/2016	Gears	5
VIN	VF7XS9HM0FZ037986	Last service miles	15,567	Doors	6
Body Style	Panel Van	MOT Due	12/10/2025		

£100 ADDITIONAL FEE Last service 08/06/2016 @ 15567 miles (1 MAIN DEALER SERVICE)


### Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips





3: Wing nsf  
Dented  
With Paint Damage



4: Door nsf  
Scratched  
Over 25mm Thru Paint



5: Door nsr  
Scratched  
Over 25mm Thru Paint



6: Sill ns  
Scratched  
Over 25mm Thru Paint



7: Qtr Panel nsr  
Dented  
With Paint Damage



8: Boot Lid  
Dented  
Over 30mm



9: Qtr Panel osr  
Dented  
Over 30mm




10: Door osr  
Dented  
With Paint Damage



11: Door osf  
Dented  
With Paint Damage



12: Wing osf  
Chipped  
1 To 5



13: Roof  
Scratched  
Over 25mm Not Thru Paint



14: Seat Base Cover osf  
Torn  
Over 3mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Poor

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK