



# VEHICLE INSPECTION REPORT

**BD16EHM**

## Jaguar XE 2.0d Portfolio 4dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	23/07/2016	Body Style	Saloon	Last service miles	75,074
Year	2016	Keys	2	MOT Due	12/04/2027
Mileage	78,630 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	8
Colour	BLACK	Number of stamps	7	Doors	4
VIN	SAJAB4AN0GA923505	Last service date	29/01/2026		

### £100 ADDITIONAL FEE

last service 29/1/26 @ 75,074 miles (7 services 2 main dealer)  
 Tensioner - timing belt replaced on 29/1/26 @ 75,074 miles  
 mileage incorrect in 2019 on mot history  
 16/04/2021 Invoice - mileage incorrect Noisy engine  
 Power steering assistance reduced message on dash

### Tyres

NSF
NSR
OSF
OSR
Spare

## Features


- Bluetooth connection
- Park assist camera
- Digital radio
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Electric door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Door osf  
Chipped  
1 To 5



2: Door osf  
Chipped  
Edge Chip



3: Door osr  
Chipped  
1 To 5



4: Qtr Panel osr  
Chipped  
1 To 5



5: Bumper Rear  
Chipped  
Multiple Chips



6: Qtr Panel nsr  
Chipped  
1 To 5



7: Door nsr  
Chipped  
1 To 5



8: Door nsf  
Chipped  
Edge Chip



9: Door nsf  
Chipped  
1 To 5



10: Bumper Front  
Scratched  
UpTo 25mm Thru Paint



11: Bonnet  
Chipped  
1 To 5



12: Door nsr  
Dented  
Over 2 UpTo 10mm

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	Fault