

VEHICLE INSPECTION REPORT

AP15FYS

Suzuki Celerio 1.0 SZ4 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
 GRADE
4

Details

Reg. date	23/06/2015	Body Style	Hatchback	Last service miles	10,744
Year	2015	Keys	1	MOT Due	24/08/2026
Mileage	59,591 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	2	Doors	5
VIN	MMSLFE42S00113185	Last service date	13/06/2017		

Last service 13/06/2017 at 10,744 miles- 2main dealer services Clutch slipping

Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	Damaged
OSF	BUDGET	2.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Rear wiper
- Air conditioning
- Metallic Paint
- Traction control
- Cloth seat trim
- Radio/CD
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Body coloured bumpers
- Rear electric windows
- Drivers airbag
- Central locking
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Thru Paint



2: Wheel of
Corroded
Light



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Scratched
UpTo 25mm Thru Paint



6: Door osr
Chipped
1 To 5



7: Qtr Panel osr
Chipped
Edge Chip



8: Wheel osr
Corroded
Light



9: Bumper Rear
Chipped
Multiple Chips



10: Tailgate
Chipped
1 To 5



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Wheel nsr
Corroded
Light



13: Door nsr
Scratched
Over 25mm Thru Paint



14: Door nsf
Chipped
1 To 5



15: Wheel nsf
Corroded
Light



16: Bumper Front
Scratched
25 to 100mm Thru Paint



17: Bonnet
Dented
With Paint Damage



18: Screen Front
Chipped
UpTo 10mm



19: Roof
Chipped
1 To 5



20: Sill ns
Scratched
Over 25mm Thru Paint



21: Tyre nsr
 Damaged
 Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK