



VEHICLE INSPECTION REPORT

HY67LUZ

Nissan Juke 1.6 N-Connecta 5dr Xtronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	15/07/2017	Body Style	Hatchback	Last service miles	46,487
Year	2017	Keys	2	MOT Due	31/08/2026
Mileage	53,994 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	8	Doors	5
VIN	SJNFBAF15U7361473	Last service date	17/09/2025		

Last Service - 17.09.2025 at 46487 miles (8 services) Gearbox fault

Tyres


NSF	GOODYEAR	5.0mm
NSR	SUNNY	5.0mm
OSF	HANKOOK	4.0mm
OSR	SUNNY	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
Up To 25mm Thru Paint



8: Bumper Rear
Scratched
Up To 25mm Thru Paint



9: Door osr
Chipped
Edge Chip




10: Door osf
Chipped
1 To 5



11: Wheel osf
Scratched
Over 50mm



12: Wing osf
Scratched
Over 25mm Thru Paint



13: Screen Front
Scratched
Over 30mm



14: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK