



VEHICLE INSPECTION REPORT

HK66YPE

Renault Captur 0.9 TCE 90 Dynamique Nav 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	23/12/2016	Body Style	Hatchback	Last service miles	92,442
Year	2016	Keys	2	MOT Due	22/12/2026
Mileage	96,095 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	GREY	Number of stamps	8	Doors	5
VIN	VF12RD11A56676393	Last service date	12/12/2025		

£100 ADDITIONAL FEE

LAST SERVICE 12/12/2025 @ 92,442 MILES (8 SERVICES, 2 MAIN DEALER - BOOK & PRINT) Front suspension knocking

Tyres


NSF	GOODRIDE	5.0mm
NSR	GOODRIDE	5.0mm
OSF	GOODRIDE	5.0mm
OSR	POWERTRAC	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Bumper Front
Insecure
Action Required



4: Door nsf
Dented
Over 30mm



5: Qtr Panel osr
Chipped
1 To 5



6: Wheel osr
Scratched
Over 50mm



7: Door osr
Chipped
Edge Chip



8: Door osf
Chipped
Edge Chip



9: Wing osf
 Scratched
 UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK