



VEHICLE INSPECTION REPORT

GP21FGM

Mini Countryman 2.0 John Cooper Works ALL4 5dr Auto

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	30/07/2021	Body Style	Hatchback	Last service miles	54,392
Year	2021	Keys	2	MOT Due	29/07/2026
Mileage	70,811 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Electronic & Paper	Gears	8
Colour	BLUE/BLACK	Number of stamps	6	Doors	5
VIN	WMW32BS0403N65248	Last service date	10/05/2025		

£90 ADDITIONAL FEE

Last service 10/05/2025 at 54,392 miles- 6 services recorded on on-board system

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR	BRIDGESTONE	5.0mm




Spare

Features


- Bluetooth connection
- Navigation system
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Door osf
Chipped
Edge Chip



3: Door osr
Chipped
Edge Chip



4: Bumper Rear
Scratched
25 to 100mm Thru Paint



5: Bumper Rear
Chipped
1 To 5



6: Qtr Panel nsr
Chipped
1 To 5



7: Door nsr
Chipped
1 To 5



8: Door nsf
Scratched
UpTo 25mm Thru Paint



9: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



10: Wheel nsf
Scratched
Over 50mm



11: Bumper Front
Chipped
Multiple Chips



12: Bonnet
Scratched
Over 25mm Thru Paint



13: Roof
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		