



VEHICLE INSPECTION REPORT

GU21JYN

Toyota RAV4 2.5 PHEV Dynamic 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	22/04/2021	Keys	2	CAP Clean	£21,050.00
Year	2021	Service history	Yes	CAP Average	£19,650.00
Mileage	75,989 Miles Warranted	Service documents	Printout	CAP Below	£18,250.00
Fuel Type	Hybrid Electric	Number of stamps	4	Gearbox	AUTOMATIC
Colour	RED/BLACK	Last service date	18/09/2024	Gears	1
VIN	JTMGBRFV40D024181	Last service miles	73,604		
Body Style	Estate	MOT Due	24/04/2026		

Last Service - 18.09.2024 at 73604 miles (4 main dealer services)

Tyres

NSF	NEXEN	5.0mm
NSR	LAUFENN	5.0mm
OSF	NEXEN	5.0mm
OSR	LAUFENN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos




1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Wing osf
Scratched
UpTo 25mm Not Thru Paint



4: Door osr
Chipped
1 To 5



5: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



6: Wheel osr
Corroded
Light



7: Bumper Rear
Scratched
Over 25mm Not Thru Paint



8: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



9: Qtr Panel Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint




10: Wheel nsr
Scratched
Over 50mm



11: Door nsr
Chipped
1 To 5



12: Wheel nsf
Scratched
Over 50mm



13: Bumper Front
Dented
Between 10mm + 30mm



14: Bonnet
Chipped
Multiple Chips



15: Wing osf
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK