



# VEHICLE INSPECTION REPORT

**VK69YOG**

## Audi Q7 45 TDI Quattro S Line 5dr Tiptronic

nama  
 GRADE  
**2**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	18/10/2019	Body Style	Estate	Last service miles	53,434
Year	2019	Keys	2	MOT Due	22/05/2027
Mileage	61,242 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	8
Colour	BLUE	Number of stamps	4		
VIN	WAUZZZ4M6LD002389	Last service date	21/05/2025		

£90 ADDITIONAL FEE

Last service 21/05/2025 at 53,434 miles- 4 main dealer services

### Tyres

NSF	GOODYEAR	6.0mm
NSR	GOODYEAR	6.0mm
OSF	GOODYEAR	6.0mm
OSR	GOODYEAR	6.0mm


### Spare

## Features


- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Wing osf  
Chipped  
1 To 5



2: Door osf  
Chipped  
1 To 5



3: Door osf  
Chipped  
Edge Chip



4: Door osr  
Chipped  
1 To 5



5: Door osr  
Chipped  
Edge Chip



6: Tailgate  
Chipped  
1 To 5



7: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



8: Wheel nsr  
Scratched  
Up To 50mm




9: Qtr Panel nsr  
Chipped  
1 To 5



10: Door nsr  
Poor Previous Repair  
Poor Paint



11: Door nsf  
Chipped  
Edge Chip



12: Bonnet  
Chipped  
1 To 5

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK