



# VEHICLE INSPECTION REPORT

**HX18XUB**

## Citroen Relay 2.0 BlueHDi H2 Van 130ps Enterprise

nama  
 GRADE  
**4**

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

### Details

Reg. date	09/06/2018	Body Style	Panel Van	Last service miles	42,562
Year	2018	Keys	2	MOT Due	19/01/2027
Mileage	70,852 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	RED	Number of stamps	1		
VIN	VF7YC2MFB12H21034	Last service date	19/01/2024		

### £100 ADDITIONAL FEE

last service 19/1/24 @ 42,562 miles (1 service)  
 mileage recorded incorrectly in 2025 on mot history

### Tyres


NSF	NANKANG	4.0mm
NSR	BRIDGESTONE	5.0mm
OSF	NANKANG	4.0mm
OSR	BRIDGESTONE	5.0mm


### Spare

## Features


- Bluetooth connection
- Air conditioning
- Cloth seat trim
- Cruise control
- Front electric windows
- Rear parking sensor
- Drivers airbag
- Digital radio
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Carpets Front  
Broken  
Replace



2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



4: Wing nsf  
Chipped  
1 To 5




5: Door nsf  
Scratched  
Over 25mm Thru Paint



6: Flasher Side Repeater ns  
Broken  
Replace



7: Door nsr  
Scratched  
Over 25mm Thru Paint



8: Door nsr  
Dented  
Between 10mm + 30mm



9: Qtr Panel nsr  
Dented  
Over 30mm



10: Tailgate  
Dented  
With Paint Damage



11: Qtr Panel osr  
Dented  
With Paint Damage



12: Panel Front  
Dented  
Over 30mm



13: Door osf  
Scratched  
Over 25mm Thru Paint



14: Door osf  
Dented  
2 Or Less Up To 10mm



15: Wing osf  
Chipped  
1 To 5



16: Screen Front  
Chipped  
Over 10mm



17: Roof  
Dented  
Over 30mm

**Interior**

**Carpet Condition**                      Poor  
**Seat Condition**                        Average

**Upholstery Condition**              Average  
**Odour**                                      No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK