



# VEHICLE INSPECTION REPORT

**OV17EJA**

## Land Rover Discovery Sport 2.0 TD4 180 HSE Luxury 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	22/03/2017	Body Style	Estate	Last service miles	67,569
Year	2017	Keys	2	MOT Due	16/02/2027
Mileage	70,131 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Printout	Gears	9
Colour	RED	Number of stamps	9		
VIN	SALCA2AN3HH692731	Last service date	16/10/2025		

£100 ADDITIONAL FEE

last service 16/10/25 @ 67,569 miles (9 services 4 main dealer) Noisy when going into the gears  
 7 seater  
 Glass roof cracked

### Tyres

NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Poor Previous Repair  
Paint Flake



2: Bumper Front  
Poor Previous Repair  
Paint Flake



3: Wheel nsf  
Scratched  
Up To 50mm



4: Wing nsf  
Chipped  
1 To 5



5: Door nsf  
Chipped  
1 To 5



6: Door nsr  
Chipped  
1 To 5



7: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



8: Qtr Panel osr  
Chipped  
1 To 5



9: Wheel osr  
Scratched  
Up To 50mm



10: Door osr  
Scratched  
Over 25mm Thru Paint



11: Door osf  
Scratched  
Over 25mm Thru Paint



12: Wing osf  
Chipped  
1 To 5



13: Wheel osf  
Scratched  
Over 50mm



14: Screen Front  
Chipped  
UpTo 10mm



15: Glass Roof  
Cracked  
Replace

### Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK